


FARAD[®] made in Italy


Evolution Srl unipersonale, Via A. De Gasperi 26, 12040 Sanfrè (CN) Italy

www.faradworld.com

+39 0172 58575




Instruction manual




KIT PR25 - 6

- | | | | | | |
|----|--|-------------------------|---|--|-------|
| A1 | | | G | | Nr. 4 |
| A2 | | COD. 91141/57 → Nr. 1+1 | H | | Nr. 4 |
| B | | COD. 91141/59 → Nr. 2 | I | | Nr. 4 |
| C | | → Nr. 4 | L | | Nr. 4 |
| D | | TCEI 8 x 18 → Nr. 4 | M | | Nr. 1 |
| E | | M8 → Nr. 8 | N | | Nr. 4 |
| F | | M8 → Nr. 4 | Y | | Nr. 4 |


1





2



FRONT BAR





PR 25 ANT + 1



PR 25 ANT + 2

3



KIT LINK




OR




KIT COMPACT


4




5



6




7




NO COMPACT

8



NO COMPACT


9



10

X4

Y





G




11


FRONT



REAR





FAILURE OBSERVE THIS NOTE CAUSES GLASS BREAKAGE





FRONT


REAR




SUNROOF SIGN




INSIDE RECIVER
Correct fitting



OUTSIDE RECIVER
Wrong fitting




Make sure the clip is well engaged inside the metal receiver under the glass.
Clip well fitted must not be able to move back and forth.
Repeat this check controll at all 4 fix points









FAILURE OBSERVE THIS NOTE CAUSES GLASS BREAKAGE

12



13





Security Regulations

